

FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2A




FIG. 2B




FIG. 3A




FIG. 3B




FIG. 3C




FIG. 3D




FIG. 3E










FIG. 4

表記 外觀状態 ポイド割合	A		5%以下
	B		10%程度
	C		20%程度
	D		40%程度
	E		60%程度
	F		80%以上